



Some Innovations

Models and Charts

























































MANAGEMENT & GRAMOTHAN, JAIPUR

LIGHTING SUGGESTIONS


- Remember to switch OFF the lights and electrical items when you leave the laboratory.
- If you see an empty laboratory, with the lights ON, please turn them OFF.
- Avoid unnecessary lighting, like in an unoccupied room or when there is sufficient sunlight.
- Promote LED lighting because not only they are energy efficient, they can be tuned more easily to specific wavelengths.





- Take advantage of natural lighting, which has positive effects on well being.
- Light personal desks/working space rather than whole room where possible.
- Turn OFF any electrical item whenever not required, such as electrical motor and lights, as well as computer equipment and analytical equipment.

Submitted to-Mr. Pramod Jain **Asst. Professor** Dept. of Mechanical Engg. Submitted by-Gaurav Gupta (16ESKME301) Abhishek Pradhan (16ESKME302) Pulkit Jain (16ESKME303)





OPTICAL FLAT

on a map. A flat surface is indicated by a pattern of straight, parallel fringes with equal spacing, while other patterns indicate uneven surfaces. Two adjacent fringes indicate a difference in elevation of one-half survivolength of the light used, so by counting the fringes differences in elevation of the surface can be



SUBMITTED TO: MR. PRAVEEN SARASHWAT MRS. MONIKA KHURANA

SUBMITTED BY: SHUBHAM KOTHARI(55) PRATEEK AGARWAL(39)


WORKPLACE LAYOUT



MR. SURIL KUMAR

Bench top 508 mm

SKIT - JAIPUR **OPERATIONS OF CENTRE LATHE MACHINE**





FACING

TURNING



DRILLING

TAPER TURNING







CHAMFERING

KNURLING





GROOVING


SUBMITTED BY: **GROUP-G2**

HARISH KUMAR HAR SH VARDHAN SINGH CHUNDAWAT - 44

- 45


HIMANSHU GOYAL HIMANSHU PARMAR

BO RING **THREADING**





PEDESTAL GRINDER



SUBMITTED TO: Sudesh Garg

SUBMITTED BY: Manas Jain, Manan Jain, Naveen Baloda, Mansi Kataria, Meenakshi Meena

PLUG GAUGE & SNAP GAUGE





Submitted To Mrs. Monika Khurana Mr. Parveen Saraswat

Submitted By Rahul Tyagi Saksham Mathur



Swami Keshvanand Institute of Technology Management & Gramothan, Jaipur




DEPARTMENT OF MECHANICAL ENGINEERING

Atomic Packing Factor (APF):SC


APF = Volume of atoms in unit cell* Volume of unit cell *assume hard spheres

APF for a simple cubic structure = 0.52



ATOMIC PACKING FACTOR: BCC

APF for a body-centered cubic structure = 0.68



APF for HCP

Atomic Packing Factor: FCC

for a face-centered cubic structure = 0.74 maximum achievable APF Close-packed directions: length = $4R = \sqrt{2} a$

Unit cell contains: 6 x 1/2 + 8 x 1/8 = 4 atoms/unit cell

C=1.633a Number of atoms in HCP unit cell= (12*1/6)+(2*1/2)+3=6atoms Vol. of HCP unit cell= sites area of the hexagonal face X height of the hexagonal Area of the hexagonal face=area of each triangle X6


unit cell

APF= $6 * \frac{4\pi r^3}{3} / (\frac{\sqrt{3}}{4} * 6 * 1.633 * a3)$ APF=0.74

Submitted to:-Mr. Keshav Jakhotia

Submitted By:- (Group - 6)
1. Tirupati Singh(ME172)


2. Veerendra Singh(ME176)








Arendra Singh Ankit Sain








Geometry of Plane Milling Cutter PRIMARY CLEARANCE ANGLE SECONDARY CLEARANCE ANGLE ANGLE ANGLE ANGLE ANGLE ANGLE CUTTING EDGE Submitted to: Mr. Yogesh Sharma Submitted by: Amit Agrawal Anay Mathur

Aman Rawat

Anirudh Singh







USED FOR MAKING INDENTATION MARKS FOR LOCATING CENTER POSITION FOR DIVIDERS. IT HAS A TAPER ANGLE OF 30

AND CENTERING HOLE SE DRILLED. IT HAS A ANGLE OF 90

us blades are stimight. It is used to cut 22 SWG or lighter sheets along straight line.

Blades are curved back from the cutting edges; it is used to cut discs and round articles from sheets.

Prick punch

STRAIGHT SNIP

(a) General purpose, face >> is slightly curved, and CENTER PUNCH head is round

> (b) It has square flat face, >> used for flattening of

These are used

for cutting sheets,

rivets and bolts.

bending of sheets, smoothening of sheets,

Hammers are used for

locking of joints and riveting

(a) Made of good quality of wood or plastic used whenever light force is required



SQUARE FACE HAMMER

MALLET

BALL PEEN HAMMER sharp and hardened to make lines on metallic sheet

> It is L-shaped piece of hardened steel, used to

different sizes

could be steel

foot rule, folding

make square corners, christing STEEL SQUARE




















Socket Set

Used for

loosing &


Tightening








Submitted by Narendra jhajhria, Mudit, Mohan, Nemish Bhatt, Nimish Shukla, Mrityunjay, MD. Fadahiqubal, MD. Nadim Akhtar






Submitted By :-Kirti Meena


Kratika Agarwal Lavesh Tiwari







- A MAIN STATE OF SHILLY 2 MEAD
 - 3 GEAR BOX CONTROLS
 - 4 DRIVING CLUTCH CONTROLS
 - 5 CHUCK
 - 7 TOOL POST
- 9 CROSS SLIDE
- AND SURFACING
- 11 SCREW CUTTING ENGAGE
- 13 CARRIAGE
- 14 DEAD CENTER
- 15 RAMP CLAMP
- 16 TAIL STOCK
- 17 LEAD SCREW
- 18 FEED ROD
- 19 GAP PIECE
- 23 STUDS SUMP
- 21 FEED BOX
- 22 TRAY






























SAFETY PRECAUTIONS TO BE FOLLOWED IN MECHANICAL WORKSHO

Major Shop Hazards

Burns:

- Hot materials and work piece from welding, torch cutting and heat-treat operations
- · Welding radiation (similar to sunburn)
- · Electric shock
- · Eye Injuries
- · Welding rays
- · Chips from machining operations, broken tools
- · Chemicals splashed in eyes, chemical fumes

Chemicals

- · Skin and eye contact
- · Inhalation of toxic fumes
- · Explosion/fire

Cuts. Abrasions:


- · Sharp edges on stock or work piece
- · Cutting tools
- · Pinch points
- · Chips from machining operations

Slip and Fall Accidents

· Coolant and oil spills

Air hoses - cords - welding cables - cluttered work area


Submitted to-Yogesh Kumar Sharma Submitted I Anop Mundo Ankur Shan Arendra Sia Ankit Sain




SAFETY PRECAUTIONS FOR MACHINE SHOP

- Safety Glasses must be wron at all thoses to prevent eyes from flying chips.
- Know how to stop the machine tool before you attempt to start the machine.
- Loose clothing, long hair, ties, personal stereo wires and jewelry may become entangled in rotating equipment leading to serious injury or death so remove or securely fastened to avoid entanglement.
- Do not touch Lathe tools by fingers as they can be extremely sharp & may get cut fingers severely.
- The chips produced in the lathe can also be razor sharp. Use extreme
 caution when removing lathe chips. Always use a brush to clean a
 machine. Do not use compressed air to blow the chips off of the machine.
- Never attempt to measure parts or clean the machine while the work piece is rotating.
- The spindle must be completely stopped before attempting to change from low gear to high gear or vice versa.
- Make certain that the work piece is securely damped in the lathe chuck or face plate or table of machine.
- Before powering up spindle, make certain all loose hand tools such as chuck keys, wrenches and measuring tools have been removed from the machine and put in the proper location.
- Calculate the proper spindle speed and feed rate before beginning a cut.

Submitted to-Yogesh Kumar Sharma Submitted by-Anop Mundel Ankur Sharma Arendra Singh Ankit Sain





Dial Gauge




Submitted To Mrs. Monika Khurana Mr. Praveen Saraswat

Submitted by Mayank Ranka Mayank Jangid

Terminology of gear tooth




Submitted to Mr. Ajay Dhanopia Mr. Promod Jain Tec. Mukesh Kumar



Submitted By Himanshu Khandelwal Jalak Bhatt Justin Varghise Kanhaiya Lal Jat


PORTER GOVERNOR



SUBMITTED TO.


MR. AJAY DHANOPIA SIR

MR. PRMOD JAIN SIR



RAJAT JANGIR
RAJESH NITHARWAL
RAJNISH DOODI
RAVI RANJAN










PLUG GAUGE & SNAP GAUGE






Submitted To Mrs. Monika Khurana Mr. Parveen Saraswat Submitted By Rahul Tyagi Saksham Mathur


TYPES OF Welding Joints DOUBLE BEVEL DOUBLEY SINGLE WELDING BOTH SINGLE V SINGLE : OPEN CORNER SINGLE EDGE SINGLE V JOINTS SQUARE 0 DOUBLE FILLET SINGLE FILLET SINGLE DOUBLE DOUBLE BEVEL DE BY: JYOTI YADAV, JAGMOHAN, JITENDRA, HIMANK HARSHITA, JAIPRAKASH,







SWAMI KESHVANAND INSTITUTE OF TECHNOLOGY, **MANAGEMENT & GRAMOTHAN, JAIPUR**

FOUR STEP SLIDING MESH GEAR BOX







Mrinal Mathur(15ESKM109) Naman Pathak(15ESKME111)

Narendra Bhandari(15ESKME112)

Narendra Singh(15ESKME113)



Submitted to:-Mr. Pramod Jain (Assistant Prof.) SKIT, Jaipur

TYPES OF GEARS





PARALLEL SHAFT AND STRAIGHT TEETH



HELICAL

PARALLEL SHAFT AND CURVED TEETH



HERRINGBONE

PARALLEL SHAFT AND DOUBLE HELICAL



SPIRAL BEVEL

Mr. Ajay Dhanopia

Mr. Pramod Jain Mr. Mukesh Kumar





RACK & PINION

Submitted By Mayank Ranka Mayank Singh

SWAMI KESVANAND INSTITUTE OF TECHNOLOGY MANAGEMENT & GRAMOTHAN, JAIPUR

FOUR BAR CHAIN INVERSION





Submitted By: (i) Chandan Kumar (16ESKME045) (ii) Chinmay Trivedi(16ESKME046) (iii) Darsh Jain (16ESKME047)

Submitted To: Mr. Pramod Jain (Assistant Prof.), SKIT Jaipur



SWAMI KESHVANAND INSTITUTE OF TECHNOLOGY, **MANAGEMENT & GRAMOTHAN, JAIPUR**

LIGHTING SUGGESTIONS

- Remember to switch OFF the lights and electrical items when you leave
- If you see an empty laboratory, with the lights ON, please turn them OFF.
- Avoid unnecessary lighting, like in an unoccupied room or when there is sufficient sunlight.
- Promote LED lighting because not only they are energy efficient, they can be tuned more easily to specific wavelengths.





- Take advantage of natural lighting, which has positive effects on well being.
- Light personal desks/working space rather than whole room where possible.
- Turn OFF any electrical item whenever not required, such as electrical motor and lights, as well as computer equipment and analytical equipment.

Submitted to-Mr. Pramod Jain Asst. Professor Dept. of Mechanical Engg. Submitted by-Gaurav Gupta (16ESKME301) Abhishek Pradhan (16ESKME302) Pulkit Jain (16ESKME303)


SWAMI KESHVANAND INSTITUTE OF TECHNOLOGY, MANAGEMENT & GRAMOTHAN, JAIPUR


GYROSCOPE



Effect of the Gyroscopic Couple on an Aero-plane

- The top and front view of an aero-plane are shown in Fig.
- Let engine or propeller rotates in the clockwise direction when seen from the rear





Gyro Torque = Angular Momentum x Angular Velocity

$$\tau = I_{spin} \times \omega_{spin} \times \omega_{prec}$$
 [Nm]

T is the gyro torque [Nm]

Itpin is the flywheel rotational moment of inertia about the spin axis [kg.m²]

ω_{spin} is the spin speed or spin angular velocity [rad.s¹]

ω_{prec} is the precession angular velocity or precession rate [rad.s.*]

Submitted to:-

Mr. Pramod Jain (Assistant Prof.)

SKIT, Jaipur

Navdeep Singh Nathawat (15ESKME114)

Nitin Lamoria (15ESKME117)

Nitin Mishra (15ESKME118)

Nitin Pareek (15ESKME119)

SUBMITTED TO :-

AJAY DHANOPIA SIR

Mr. PRAMOD JAIN

Synchromesh Gear Box











SUBMITTED BY :-AMOL DHUPAR ANKIT SOLANKI ANSHUL TAILOR ANSHUMAN SINGH JADOUN

SWAMI KESHVANAND INSTITUTE OF TECHNOLOGY, JAIPUR DEPARTMENT OF MECHANICAL ENGINEERING Legarision lark and cap Picase to heater from block How the coolant co-A local water covering to all will be a fact to the passes from long per and the excellent and the person and the excellent are that a spring-baded views after these states a Water gump HEATER HETURN HOSE PLUGS COOLANT DEAN FLUG AUTOMATE COOLIN LINES COOLING SYSTEM Submitted By: Rahul Bagla, Rahul Garg Batch: B1

Faculty Name: Asshish Nayy ; Chandan K. Gupta










Figure 1. Electric Arc Welding



